

FIG. 1 is a schematic diagram of a system 10 for monitoring a process. The system 10 includes a plurality of sensors 14, 16, 18, and 20. The sensors 14, 16, and 18 are arranged in a vertical column, and the sensor 20 is arranged horizontally. The sensors 14, 16, and 18 are connected to a central processing unit 12, and the sensor 20 is connected to a central processing unit 11. The central processing unit 12 is connected to a display 13, and the central processing unit 11 is connected to a display 17. The system 10 is used to monitor a process and provide real-time feedback.




Figure 1




Figure 2




Figure 3




Figure 4